

# **ASSEMBLY INSTRUCTIONS**

# Wood Top Work Tables With Undershelf

# **4 LEG TABLE**

#### **PARTS:**

- (1) Wood Top
- (4) Leg Gussets
- (4) Legs
- (1) Shelf

### **HARDWARE:**

(16) 1" Lag Screws

#### **TOOLS REQUIRED:**

- (1) 4mm HEX Wrench (Included)
- (1) 3/8" Socket Wrench

#### **6 LEG TABLE**

#### PARTS:

- (1) Wood Top
- (6) Leg Gussets
- (6) Legs
- (1) Shelf

#### **HARDWARE:**

(24) 1" Lag Screws


#### **TOOLS REQUIRED:**

- (1) 4mm HEX Wrench (Included)
- (1) 3/8" Socket Wrench



## **ASSEMBLY INSTRUCTIONS**

- 1. Make sure the assembly area is clean and on a flat secure surface. Carefully remove all the contents within the box. Place the wood top face down on a rug, carton or other protected surface.
- 2. Using a socket wrench and the provided 1" lag screws, attach the leg gussets to the pre-drilled holes in the wood worktop. It is recommended that the gussets be turned so the set screws are positioned toward the center of the table.
- 3. Loosen the set screws on the leg gussets to allow the legs to be inserted. Place the legs into the leg gussets. Do not tighten set screws until later.
- 4. With assistance, place shelf face down with the legs sliding through the shelf gussets. Adjust the shelf to your desired height and tighten the set screws using the provided hex wrench. Do not overtighten.
- 5. Tighten the set screws on the leg gussets. Do not overtighten
- 6. For the table to be NSF Certified, you must fill all the set screws with silicon caulk.
- 7. With assistance, grasp the table by the top and turn the table right side up. Adjust the feet to level the table. The table is now ready to be used.





0222