


WIRING DIAGRAM



AX-M60 THREE PHASE